


YERASOV MUSIC CORPORATION
www.yerasov.ru e-mail: sale@yerasov.ru



SCREAMER

GT-10

Guitar pedal



User manual

YERASOV.

FOR NOTES

PACKAGE CONTENTS

- 1
- 1

SAFETY MEASURES

- Keep away from high humidity.
- After exposure to cold, keep the device at room temperature for at least 30 minutes before switching on.
- Avoid dropping, keep away from dirt and water.

OVERVIEW

GT-10 is a classic tube screamer distortion effect that can be used as a standalone effect with true bypass mode as well as an additional gain control for a tube amp.


Built with the best available components on the market (WIMA film capacitors, low-noise chips, precision resistors, electrolytic capacitors with low leakage currents and a 2DPDT Alpha footswitch) GT-10 doesn't interfere with the natural tone of the amp while significantly enhancing the sustain level.

1

APPLICATION


The pedal is powered by either a 6F-22 battery or a 9V DC adapter. We recommend using YERASOV AD9-100 or AD9-400 adapters. For extended battery life unplug the guitar cable when device is not being used.

1. Install battery or plug the adapter in.
2. Connect the pedal as shown in the illustration.
3. Turn the guitar volume knob to the maximum level for best results.
4. The LED light indicates that the pedal is turned on.
5. When used as an amplifier booster start off with the DRIVE control at the minimum level.




3

PANEL DESCRIPTION



- 1 - Output Jack
- 2 - **VOLUME** - volume level
- 3 - **TONE** - tone control
- 4 - DC adapter input
- 5 - On / Off LED indicator
- 6 - **DRIVE** - distortion level
- 7 - **FAT / DRY** - bass boost toggle switch
- 8 - Input Jack
- 9 - On / Off Switch

CONNECTION POLARITY OF DC ADAPTER



2

SCS PEDAL BOARD

YERASOV GT-10 is compatible with SCS Pedal Board. The SCS connector is at the bottom of the pedal, the cable is included in the SCS Pedal Board package. For more information please visit www.yerasov.ru

BATTERY REPLACEMENT

Access the battery compartment by unscrewing the bottom cover. Always put the cover back after replacing the battery.

SPECIFICATIONS

Input impedance, kOhm.....	510
Power supply (battery / DC), V.....	9
Current Draw, mA.....	12
Dimensions, mm.....	112 x 62 x 50
Weight, kg.....	0,25

4